

कार्यकारी अभियंता,  
सार्वजनिक बांधकाम विभाग, मिरज.  
मिरज. ४१६ ४१०

Phone No. (०२३३)२२२२६६५

Fax No. (०२३३) २२२३७६५

Web Site-www.mahapwd.com

E-Mail :- miraj.cc@mahapwd.com

जा.क्रं./प्रकल्प/इमारती/ ५४४३ /२०२१

दिनांक :- २३ AUG २०२१

प्रति,

मुख्यध्यापक,  
तक्षिला स्कूल, १०० फुटी रोड,  
सांगली.

विषय इमारत Stability (Safety) प्रमाणपत्र मिळणेबाबत.

संदर्भ सहाय्यक कार्यकारी अभियंता वर्ग-१, सार्वजनिक बांधकाम उपविभाग, सांगली  
यांचे पत्र जा.क्रं. वि.शाखा/८७८/२०२१ दिनांक ०५/०८/२०२१

उपरोक्त विषयास अनुसरून सदरभिय पत्रान्वये तक्षिला स्कूल, १०० फुटी रोड, सांगली यांनी इमारत  
Stability (Safety) प्रमाणपत्र मिळणेबाबत अर्ज केला होता. त्यानुसार दिनांक १९/०७/२०२१ रोजी सदर इमारतीची  
सहाय्यक कार्यकारी अभियंता वर्ग-१ यांनी पाहणी केली असता सदर इमारत तळमजला + तीन मजले अशा स्वरूपाची  
असून सुस्थितीत असलेबाबत सदरभिय पत्रान्वये कळविले आहे.

सोबत प्रमाणपत्र सादर करीत आहे. हे आपले माहितीसाठी.

सोबत- प्रमाणपत्र प्रत

कार्यकारी अभियंता  
सार्वजनिक बांधकाम विभाग, मिरज

प्रत:- सहा. कार्यकारी अभियंता वर्ग-१, सा.बां.उपविभाग, सांगली यांना माहितीसाठी रवाना..



*Palase*  
Principal,  
Takshila School  
South of Shri  
Datta Sai Mandir,  
Sangli-416 416


## BUILDING SAFETY CERTIFICATE


This is to certify that the building of Takshila School, Sangli situated at South of Shree Datta Sai Mandir, 100 Feet Road, Sangli is inspected by me and Sectional Engineer P.W. Section, Vishrambag, Sangli.

At present the G+4 school building is in order for educational purpose under normal circumstances based on visual inspection by this office. However the safety of building with respect to R.C.C. design should be checked from the consultant appointed by the school management. The compliance for the following points should be made.

- 1) Railing should be provided for existing ramp.

Counter Signed

  
Assistant Executive Engineer Class-1  
P.W. Sub-Division, Sangli.

  
Executive Engineer  
P.W.Division, Miraj,

No. DB/Building/3883/2021

Office of the Executive Engineer

P.W.Division, Miraj

Date:- 23/04/2024



  
Principal,  
Takshila School  
South of Shri  
Datta Sai Mandir,  
Sangli-416 416